

WANTED - new or second hand !

I am desperately looking for an axle half shaft for my Australian OKA 4x4 truck. Please help!

My left side half shaft at the rear axle broke (please see attached pictures).

The **shaft is on the left side of the Dana 70 rear axle.**

Please check below numbers with caution, some are very difficult to read.

Info on axle tube:



070A? 150 1

334 94



ML74QE2662A317 7NA

Info on top diff housing:



12 K ? ?

42935

R ? ?

Info on flanges:



Right shaft:

(BROKEN)

43811-9?

?S226D

Left shaft

43811-11

? R220D

Right shaft:

length from inside the flange is 925mm

Left shaft (BROKEN):

Length from inside the flange is approx. 865mm

Splines: 32

Spline length: 45mm

Holes in flange: 8

Flange holes distance (two opposed holes): 101mm

Please help with supplying the half shaft!

Please contact Grischa:

grischa.roehrig@gmail.com

Mobile South Africa: +27 820 646523

Skype: north_island

South Africa